

Audi A5

Located in: Poland

Vehicle reference:
WAULFAFR4EAXXXXXX

Model year: 2014
Body type: Coupe
Fuel type: Petrol
Engine size: 1984 cm3
Engine power: 162 kW / 220 hp



Get [American report!](#)



Salvage title issued



Accident reported



Imported vehicle



Number of odometer readings: 8



Quick Check

| | |
|--|---|
| Stolen Not reported stolen | ✔ No issues reported |
| Identity check Not reported scrapped | ✔ No issues reported |
| Damage Accident reported | ! Accident |

A CARFAX Vehicle History Report is based only on information supplied to CARFAX. Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Highlights

Owners in Poland

Number of owners:
2

Number of transfers: 1

Odometer

128315
Last reported: 2021-09-07

Vehicle age

8 years
Vehicle year: 2014
First registration date: 2014-07-01

Inspections

Latest inspection:
2021-09-07

History information

| Date | Mileage | Event |
|--|--------------------------|--|
| 2014-07-01 | | First registration abroad |
| 2014-08-21 | 65 mile 105 km | Odometer reading reported |
| 2015-10-04 | | Accident reported in United States |
| <div style="border: 1px solid red; padding: 5px;"> <p>▲ Accident This vehicle has had an accident. Have it inspected by a mechanic before purchasing.</p> </div> | | |
| 2015-11-25 | 18,511 mile 29,790 km | Insurance claim reported in United States Salvage title was issued in United States |
| <div style="border: 1px solid red; padding: 5px;"> <p>▲ Salvage Title This vehicle had a Salvage title issued in the USA. Check the condition of the vehicle with a mechanic before purchasing.</p> </div> | | |
| 2015-12-27 | | Imported from United States to Lithuania |
| 2016-02-15 | | Damage reported in Lithuania Damaged area: • Vehicle damaged on all sides Damage reported for: • Airconditioning • Windshield / Glass • Upholstery • Passive safety systems • Chassis • External Lighting • Suspension System • Active safety systems • Body parts |
| 2019-08-29 | 94,000 km | Damage reported in Germany Damaged area: • Right front • Front Damage reported for: • Body parts |
| 2020-06-17 | | Accident reported in Germany Damaged area: • Right front • Front • Left front Damage reported for: • Airconditioning • Chassis • External Lighting • Active safety systems • Body parts |
| <div style="border: 1px solid red; padding: 5px;"> <p>▲ Accident This vehicle has had an accident. Have it inspected by a mechanic before purchasing.</p> </div> | | |
| 2020-06-22 | 116,500 km | Odometer reading reported |
| 2020-09-09 | 116,720 km | Inspected in Poland Inspection type: regular Inspection passed |
| 2020-09-15 | | Imported from Germany to Poland Registered in Poland New owner reported Owner type: private individual |
| 2021-08-16 | 128,000 km | Damage reported in Poland Damaged area: • Left rear • Rear |
| 2021-08-18 | 127,830 km | Odometer reading reported |
| 2021-09-07 | 128,315 km | Inspected in Poland Inspection type: regular Inspection passed |
| 2021-09-15 | | Damage reported in Poland Damaged area: • Left rear • Rear |
| 2021-09-19 | | Vehicle insured Liability insurance valid until 2022-09-18 |
| 2022-02-14 | | Damage reported in Poland |
| 2022-05-11 | | New owner reported Owner type: private individual |

Based on data reviewed from 22 countries in Europe and North America

CARFAX Glossary

Model year

This term is defined by the manufacturer but it is typically the year the vehicle is built. If the model year does not appear on the CARFAX report, it is because the manufacturer did not include this information in the VIN. Model year can normally be determined by the vehicle age.

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.