

Volkswagen Passat

VIN: 1VWBN7A35CCXXXXXX

2014



Theft



Usage



Odometer



Financial and legal
status




Damage



Photos

2017-04

8 photos





Usage

Was the vehicle used as a taxi, rental, or other service vehicle? Note: such vehicles may be in worse condition than usual!



Vehicle was used as a rental!

Here's what we checked:



Rental

⚠ Record found

Rental vehicle



Taxi

✓ No record found

No evidence of being used as a taxi



Transport

✓ No record found

No evidence of being used as a transport vehicle



Police

✓ No record found

No evidence of being used by police



Handicap

✓ No record found

No evidence of being used as a handicap vehicle



Driving school vehicle

✓ No record found

No evidence of being used as a driving school vehicle

Theft

Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?




Vehicle may be stolen!

Here's what we checked:



Currently wanted as stolen

⚠ Record found

Unknown date  Lithuania



Stolen in the past

✓ No record found

Current status unknown



Stolen in the past

✓ No record found

Vehicle has been recovered

Police database stolen vehicle **check completed in:**



Lithuania

⚠ Record found



Czechia



Hungary



Italy



Norway

Odometer

Are there signs of mileage rollbacks or discrepancies?



This vehicle may have a fake mileage!



Last known mileage: 145,000 km



Average mileage for similar models: 104,200 km



5 mileage records found



Odometer records

2014-01	102,000 km
2015-01	129,000 km
2016-02	155,000 km
2017-12	136,000 km
2018-09	145,000 km

 Odometer Rollback

Odometer brand checks

May Be Altered

 Record found

Actual

✓ No record found

Not Actual

✓ No record found

Tampering Verified

✓ No record found

Exempt from Odometer Disclosure

✓ No record found

Exceeds Mechanical Limits

✓ No record found

Replaced

✓ No record found

Call Title Division

✓ No record found

Financial and legal status

Has the vehicle passed its technical inspections? Does it have property rights restrictions or outstanding loans?



Tech inspection is valid

Legal



Technical inspection

Passed 2017-02



Has successfully passed technical inspection



Scrap

✓ No record found

No record that vehicle was marked as scrapped



Exported

✓ No record found

No export records found



Imported

✓ No record found

No import records found

Financial restrictions



Lease

✓ No record found

No data available on outstanding loan or finance agreement



Operating-lease

✓ No record found

No record of vehicle being on an operating-lease



Unit-stocking

✓ No record found

No record of vehicle being under unit-stocking finance

Damage

Has this vehicle been damaged in the past? What was the value of the damages?



This vehicle was damaged 3 times!



This vehicle was severely damaged!



Severe damages can leave structural issues, making the vehicle unsafe to drive!

Damage records



Front right bumper

Severe damage


2018-03

Estimated Repair Cost

€17,000

Possible Damage Cause

Unknown



Severe damage

2014-02

Estimated Repair Cost

€10,000

Possible Damage Cause

Unknown



Damage

2014-02

Estimated Repair Cost

€1,000

Possible Damage Cause

Unknown

Specs & equipment

What specs and equipment are on record for this vehicle?



Check whether the specs and equipment of this vehicle match the facts given by the seller.

Identification and technical specifications



Make

Volkswagen



Model

Passat



Body type

Sedan



Manufacture year

2014



Powertrain displacement

1.968 L



Powertrain power

103 kW (138 hp)



Transmission type

Automatic



Plant location

Germany

Equipment

E0A

Special editions

No special edition

1PA

Lockable wheel bolts

Standard wheel bolts

0DI

Vehicle class differentiation units/platform components

Vehicle class differentiation -360-

1D0 Trailer hitch
Without trailer hitch

1E1 Activated carbon canister
Activated carbon canister

6XU

Exterior mirrors
**automatically dimming, electrically adjustable,
separately heated**

5SL Left exterior mirror
aspherical

1X0 Drive layout
Front wheel drive

A8B Equipment levels
Basic equipment

J0L Batteries
Battery 340 A (70 Ah)

4M3 Beverage holders
Cup holder

B0A

Component part sets with country-specific design requirements
Component parts set without country-specific design requirement

1AT Brake systems
Electronic stabilization program (ESP)

9Z0 Operating voltage
Operating voltage 12V

7QA CD ROM/DVD/SD card
Without CD/DVD for navigation

2H0 Charism
Without “drive select”

7MG Emissions standard
Emission standard EU5

4UE Airbag
Air bag for driver and front seat passenger

8ZH Antennas
Antenna for AM/FM reception, “diversity”

EA0 Follow-on warranty
Without subsequent warranty

5RQ Right exterior mirror
convex

9WL “Multimedia”, video/DVD/notebook connection
Multimedia socket for external audio source

1KW Brake type in rear
Disc brakes, rear

1ZM Brake type, front
Disc brakes, front (Geomet D)

NY0 Battery/alternator capacity
Standard battery/alternator capacity

1S1 Tool kit and jack
Tool kit and jack

0XR Owner’s manuals
Information kit in Lithuanian

9T0 Heated washer nozzles
Without heated washer nozzles

7A0 CD changer/CD player
Without CD changer/CD player

QJ1 Chrome package
Chrome work package

C26	General operating permit, alterations Operating permit, alteration	3S0	Roof rails/roof load rack Without roof rails/roof load rack
3FA	Roof insert/convertible top Without roof insert (standard roof)	1JA	Suspension system in rear Rear shock absorption, basic design 1
G07	Suspension system in front Front shock absorption	3X0	Ski bag Without load-through provision
2G1	Insert for the filling up of unleaded fuel/fuel type Insert for the filling up of unleaded fuel	0EM	Installation differentiation for vehicle components Installation differentiation for transmission MQ 200 vehicle components
7AL	Theft protection system Anti-theft alarm system, passenger compartment control, backup horn and towing protection	7TM	Inserts Decorative inserts
7M0	Scuff plates Plastic scuff plates in door apertures	7X0	Park distance control Without park distance control
UF0	Electric interface for external use Without electric interface	0FG	Manufacturing sequence differentiation Mosel manufacturing sequence
6A0	Fire extinguishers Without fire extinguisher	VF0	Pedal cluster Standard pedal cluster
8K3	Headlight control Separate daytime running lights with low beam assistant and "Coming Home" feature	UH2	Parking brake Parking brake
7G0	Vehicle tracing system Without preparation for VTS (vehicle tracking system)	F0A	Vehicle specifications No special purpose vehicle, standard equipment
8GG	Alternators Alternator 110 A	0G4	Transmission types/gearshift mechanisms Cable gearshift
0YC	Weight category rear axle Weight range 3 installation control only, no requirement forecast	L01	Weight category front axle Suspension range 01 installation control only, no requirement forecast
TU0	Base engine 4-cylinder gasoline engine 1.4 L unit 03C.K	6M0	Tie down straps/net/pocket Without tie down straps/net/pocket

8T0	Cruise control system Without cruise control system (CCS)	VC0	Garage door opener W/o remote-controlled garage door opener
G0K	Transmission specifications 6-speed manual transmission	6Y9	Cruise control system and speed limiter W/o cruise control speed limit system
3P1	Brackets Bracket for first aid kit and warning triangle	3NU	Rear seats Rear seat bench unsplit, backrest split folding with center armrest
KH6	Heating and air conditioning system Electronically controlled air conditioning system	8ID	Headlamps Halogen twin headlights
FC0	Customized installation Without customized installation	6T0	Interior light in footwell Without interior light in footwell
U5A	Instrument clusters Instrument insert, km/h speedometer	4L6	Breakaway interior rearview mirror Breakaway interior rear view mirror, automatically dimming
K8B	Body style Notchback	QK0	Camera/distance sensor Without camera without distance sensor (driver assistance system)
6SE	Luggage compartment floor covering Flat needle-punched trunk floor covering	4W0	Cassette and CD storage unit Without cassette and CD storage unit
QA0	Child seats Without child seat	0Y3	Climatic zones Cold zones
QR0	Compass/road sign display Without compass/traffic sign display/ traffic signs recognition	4D0	Seat ventilation/massage seat Without seat ventilation/massage seat
3Q6	Rear head restraints Three rear headrests	5ZJ	Head restraints Front headrests
1Z0	Fuel quantity for initial filling Initial standard fuel filling	1A2	Fuel systems Fuel system for SI engine with direct injection (FSI)
5C0	Body measures Without special body measures	6KJ	Radiator grille Radiator grille with chrome-plated strip

6P1 Rear license plate carrier
License plate bracket rear (ECE)

5K7

Paint preservative/transit coating

Transport protection film (minimum protection) with additional transport protection measures

FE0 Country codes
Without country code (no DVD player in vehicle)

8S7 Reading light
Two reading lights front

3H0 Backrest release
Without backrest release for front seats

2P1 Loading edge protection
Plastic trunk sill protection

1MR Steering wheels
Leather steering wheel

8RM Speaker installation
8 speakers (passive)

6E3 Center armrest
Front center armrest

3I5 Center console
Center console

8Z5 Engine cooling system
Not hot country

4SG

Left vanity mirror

Left vanity mirror illuminated extractable sun visor

7Q0 Navigation device
Without navigation device

8WA Front fog lamp/additional headlamp
Without front fog light

6W1 Front license plate carrier
License plate bracket front (large)

3GA Rear luggage/load compartment floor
Without cargo area

L0L Steering system arrangement
Left-hand drive vehicle

1N3

Steering

Speed-related variable steering assist (Servotronic)

8G0 Light control systems
Without light assistant

7P0 Lumbar support
Without lumbar support in seat backrests

AV1 Driving on the left/on the right
Driving on the right

8Q1 Headlight range control
Headlight-range adjustment

9Q5 Multi-function display/trip computer
Multi-function display with control

EM0 Driver alert system
Without Rest Assist

D4X

Engine specifications

4-cyl. gasoline engine 1.4 l/90 kW TSI Base engine is TU0/TL1/TL8/T9B

4TL

Right vanity mirror

Vanity mirror, right, illuminated extractable sun visor

8TC Rear fog lamp
Rear fog light for driving on the right

1NH Wheel covers
Full wheel covers

CZ0	Wheels Steel wheels 6.5J x 16 with optimized weight
9JA	Smoker's/non-smoker's package Non-smoking package
NS0	Umbrella Without umbrella(s)
V0A	Tire suppliers Tires w/o specification of tire brand
3QT	Restraint systems, front 3-point seat belts with tensioner and height adjustment, front
WD4	Anti-theft alarm system "Plus" True
4X3	Side airbag Side air bag front with curtain air bag
2SB	Special labels/plates Labels/plates in Polish, Estonian, Latvian, Lithuanian, Slovenian
4E2	Lock operation for tailgate/trunk lid Tailgate/trunk lid release from inside (electrically)
3SB	Front seat, right Standard seat, front right
3ZB	Outer rear seat belts 3-point seat belts, outer rear with ECE label
N4C	Seat trim covers Fabric seat covering
4A0	Seat heater Without seat heater

8AE	Radios Radio "RCD310 MP3"
7K6	Direct tire pressure monitoring system Flat tire indicator
H2F	Tires Tires 205/55 R16 91H super-optimized rolling resistance
1G2	Spare wheel/breakdown kit Steel spare wheel with original equipment tires
PA1	Leather steering wheel (3-spoke) with decorative aluminum inserts True
WFA	Family package, Passat station wagon, Sweden True
6Q2	Gearshift knob/handle Leather gearshift knob/handle
8SG	Rear combination lamps Standard taillight assemblies (type 2)
3TB	Front seat, left Standard seat, front left
9P1	Seat belt check Seat belt reminder, electric contact in buckle
3C7	Center rear seat belts 3-point seat belt for center rear seat
3L3	Seat adjustment Manual height adjustment for front seats
7L3	Start-stop system/regenerative braking Without start/stop system without regenerative braking

8Y1	Horns	QH0	Audio-response system/voice control
	Two-tone horn		Without voice control
7Y0	Lane change assist/lane keeping system	4KC	Side and rear windows
	Without lane change assistant		Side and rear windows in heat-insulating glass
4B1	Protective side molding	3Y0	Roll-up sun screen for rear and side windows
	Protective side molding		Without roll-up sun screen
7B6	Socket	2JB	Bumpers
	12-volt socket(s)		Standard bumpers
QN0	Drawers under front seats	8X0	Headlamp washer system
	Without drawers under front seats		Without headlight washer system
8N3		3M0	Special registration measures
Windshield wiper intermittent control/ light/rain sensor			Without special measures
	Windshield wiper intermittent control with rain sensor		
0NB	Nameplate set	9A0	Special alarm systems
	Nameplate set in base trim		Without taxi alarm system
1Q0	Mass damper for steering wheels	4K3	
	Without mass damper for steering wheel	Door and lid locking system	
		Radio remote controlled central locking operated from inside and safe securing	
B47		5D1	Carrier frequency for radio remote control
Type approval countries/countries with special requirements			Carrier frequency 433.92 MHz-434.42 Mhz
	Type approval the Baltic States		
3CA	Partition	NT0	Transit coating
	Without partition		Transit coating (type 1)
3LC		QV0	TV reception/digital radio reception
Door and side trim panels			W/o TV reception/digital radio reception
	Door and side trim panel in foam film and woven fabric		
1VG		1SA	Front underbody guard
Installation parts for engine (engine mount system)			Without additional front underbody guard
	Installation parts for four-cylinder engine		
1EX		2A0	Delivery equipment
Identification plates			Without delivery equipment
	Special identification plate for EC for M1 passenger vehicle		





<div>1T2</div> <div>First aid kit / warning triangle</div> <div>Warning triangle</div>	<div>9D0</div> <div>Preparation for two-way radio installation</div> <div>Without preparation for two-way radio installation</div>
<div>9F0</div> <div>Preparation for sound combination for rotating beacon</div> <div>Without sound combination for rotating emergency light and radio antenna preparation</div>	<div>9W0</div> <div>Telephone / telematics</div> <div>W/o car phone preparation/installation</div>
<div>9TC</div> <div>Additional warning lights</div> <div>Additional reflectors (door area)</div>	<div>QG1</div> <div>Service interval prolongation</div> <div>Service interval prolongation</div>
<div>7E0</div> <div>Heat accumulator system/auxiliary heater</div> <div>W/o heat accumulator/auxiliary heating</div>	<div>4GF</div> <div>Windshield glass type</div> <div>Windshield in heat-insulating glass</div>
<div>8FA</div> <div>Second battery/battery installation</div> <div>Without second battery</div>	<div>2WA</div> <div>Additional tires (snow tires)</div> <div>Without additional tires</div>
<div>0TA</div> <div>Floor mats</div> <div>Without floor mats</div>	<div>4ZE</div> <div>Decorative trims</div> <div>Black moldings</div>
<div>3B4</div> <div>Additional child seat anchors</div> <div>Child seat anchor for child seat system ISOFIX</div>	<div>9M0</div> <div>Auxiliary heater</div> <div>Without auxiliary/parking heater</div>
<div>UP0</div> <div>Clocks</div> <div>Analog clock</div>	

Timeline

5 records found

The timeline of records for this vehicle

Latest records

<div>2014-01</div> <div> Germany</div>	<div></div> <div>Was manufactured</div> <div>The country (or state) indicates either the location of the manufacturing facility, assembly plant, or registration address of the manufacturer. The date may be approximate.</div>
<div>2014-02</div> <div> Poland</div>	<div></div> <div>Was registered</div> <div>The record represents an administrative event. This could be related to a change of ownership, documents, etc</div>

2017-02

 Lithuania



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test, or emission control test) has been recorded. Both successful and failed instances may be included.

2017-11

 Lithuania



Damage detected

We have indications that this vehicle was recognised as damaged in this particular country (or state). Please refer to the “Damage” section for details.

2020-02

 Lithuania



Wanted

The vehicle was declared as stolen in this particular country (or state). It is purely the “origin of theft”, and does not cover all the jurisdictions otherwise involved.