



PRINT REPORT

SAVE AS PDF

Report Generated Date: March 20, 2016 3:49 PM EDT

Report ID: 145850338797

2007 Nissan Pathfinder

VIN:	5N1AR18W57C6****
Year:	2007
Make:	Nissan
Model:	Pathfinder
Trim:	LE 4WD
Style/Body:	SPORT UTILITY 4-DR
Engine:	4.0L V6 DOHC 24V
Made In:	UNITED STATES
Vehicle Age:	9 year(s)
Fuel:	
Default WheelSize:	
Overall Height:	72.90 in.
Overall Length:	187.60 in.
Overall Width:	72.80 in.
Tank Size:	21.10 gallon
Highway Mileage:	21 miles/gallon
City Mileage:	16 miles/gallon









Title Records

This section lists title records in chronological order.

Generated Date: March 20, 2016 3:49 PM EDT

Event Date	Source	Туре	Mileage	Details
04/11/2007				Vehicle manufactured and shipped to original dealer
05/31/2007	New Jersey			Registration issued or renewed
06/06/2007	New Jersey		299 mi	Registration issued or renewed Title #: GD200715700001930
03/14/2009	New Jersey		38,101 mi	Service contract issued

09/09/2010	Eastern Region	51,973 mi	Reported at Auto Auction
09/23/2010	Pennsylvania	51,973 mi	Registration issued or renewed Title #: 68763911
01/27/2011	Pennsylvania	52,394 mi	Registration issued or renewed
01/27/2011	Pennsylvania	52,394 mi	Front brake pads replaced Front brakes serviced Brakes checked
03/23/2011	Pennsylvania		Registration issued or renewed
03/29/2011	Pennsylvania		Registration issued or renewed
01/04/2013	Pennsylvania	69,000 mi	Registration issued or renewed Title #: 68763911 Not Actual Miles
04/10/2013	New Jersey	70,925 mi	Registration issued or renewed
04/26/2013	New Jersey	71,068 mi	Registration issued or renewed
06/03/2013			Vehicle Exported to Dominican Republic

Junk / Salvage / Insurance Records

This section lists junk, salvage, insurance records and etc. (if any).

Event Date	Reporting Entity	Details
	Copart, Inc.	Description: Junk And Salvage
12/27/2012	Fairfield, CA	Disposition: SOLD
	Phone: (707) 639-5294	Intended for Export: N
	Copart, Inc.	Description: Junk And Salvage
12/27/2012	Fairfield, CA	Disposition: TO BE DETERMINED
	Phone: (707) 639-5294	Intended for Export: N

Theft Records

This section lists active theft and theft recovery records for this VIN.

Status	Event Date	Reporting Entity	Details
(i)	03/23/2011	Motor Vehicle Dept.	Theft (Title #:68763911)
(i)	03/29/2011	Motor Vehicle Dept.	Theft Recovered (Title #:68763911)

Lien / Impound / Export Records

This section lists lien, impound, and export records (if any).

Event Date	Record Type	Details
06/03/2013	Export	Vehicle Exported to Dominican Republic

Title Checks

This section lists our checks for potential problems related to the title.

Status	Problem checked
8	No Flood damage
\otimes	No Fire damage
\otimes	No Hail damage
\otimes	No Salt water damage
\otimes	No Vandalism
8	No Kit Assembly
\otimes	No Dismantled
8	No Junk
(i)	Rebuilt Brand Date: 04/26/2013 Brander: NEW JERSEY Brander Type: State
\otimes	No Reconstructed
<u> </u>	Salvage: Damage or Not Specified Brand Date: 04/10/2013 Brander: NEW JERSEY Brander Type: State Salvage: Damage or Not Specified Brand Date: 01/04/2013 Brander: PENNSYLVANIA Brander Type: State
8	No Salvage: Stolen
8	No Salvage: Reasons Other Than Damage or Stolen
⊗	No Test Vehicle
\otimes	No Refurbished
\otimes	No Collision
8	No Salvage Retention
\otimes	No Prior Taxi

Status	Problem checked
8	No Prior Police
8	No Original Taxi
8	No Original Police
\otimes	No Remanufactured
\otimes	No Gray Market
\otimes	No Warranty Return
\otimes	No Antique
\otimes	No Classic
\otimes	No Agricultural Vehicle
\otimes	No Logging Vehicle
\otimes	No Street Rod
\otimes	No Vehicle Contains Reissued VIN
\otimes	No Replica
8	No Totaled
8	No Owner Retained

Status	Problem checked
8	No Bond Posted
8	No Memorandum Copy
8	No Parts Only
(i)	Recovered Theft Title #: 68763911

Brander: Motor Vehicle Dept, PHILADELPHIA, PA

Date: 03/29/2011

Status	Odometer Information
i	Odometer: Not Actual
\otimes	Odometer: Tampering Verified
\otimes	Odometer: Exempt from Odometer Disclosure
\otimes	Odometer: Exceeds Mechanical Limits
\otimes	Odometer: May be Altered

8	No Undisclosed Lien
\otimes	No Prior Owner Retained
\otimes	No Vehicle Non-conformity Uncorrected
\otimes	No Vehicle Non-conformity Corrected
\otimes	No Vehicle Safety Defect Uncorrected
\otimes	No Vehicle Safety Defect Corrected
\otimes	No VIN Replaced
\otimes	No Gray Market: Non-compliant
\otimes	No Gray Market: Compliant
8	No Manufacturer Buy Back
8	No Former Rental
8	No Disclosed Damage
8	No Prior Non-Repairable / Repaired
8	No Crushed

8	Odometer: Replaced
8	Odometer: Reading at Time of Renewal
\otimes	Odometer: Discrepancy
8	Odometer: Call Title Division
8	Odometer: Exceeds Mechanical Limits Rectified

Report Glossary

More information is available in the <u>full report glossary</u>.

Term	Definition
Rebuilt	The vehicle, previously branded "salvage", has passed anti-theft and safety inspections, or other jurisdiction procedures, to ensure the vehicle was rebuilt to required standards. Also known as prior salvage (salvaged).
Salvage: Damage or Not Specified	Any vehicle which has been wrecked, destroyed or damaged, to the extent that the total estimated or actual cost of parts and labor to rebuild or reconstruct the vehicle to its pre-accident condition and for legal operation on roads or highways exceeds a jurisdiction-defined percentage of the retail value of the vehicle. The retail value of the vehicle is determined by a current edition of a nationally recognized compilation (to include automated data bases) of retail values. SalvageDamage or Not Specified also includes any vehicle to which an insurance company acquires owner- ship pursuant to a damage settlement, or any vehicle that the vehicle's owner may wish to designate as a salvage vehicle by obtaining a salvage title, without regard to extent of the vehicle's damage and repairs, or any vehicle for which the jurisdiction cannot distinguish the reason the vehicle was designated salvage.
Odometer: Not Actual	The odometer reading is known to be other than the true mileage for the vehicle.
Theft	The vehicle was stolen from its legal owner.

Copyright © 2016, FAXVIN Inc. All rights reserved.